Firmware/Software compatibility:

Pi/DENEB/DALIM:
Amp Fw: v3.4.x => PC Sw v4.4.x (latest v4.4.0)
Amp Fw: v3.3.x => PC Sw v4.3.x (latest v4.3.7)
Amp Fw: v3.1.x => PC Sw v4.2.x (latest v4.2.10)
Amp Fw: v2.0.x => PC Sw v4.0.x (latest v4.0.10)

Change log:
v4.4.5.0
Required Firmware:
Pi/DENEB/DALIM: v3.4.x (the included FW_Updater updates Pi/DENEB/DALIM to v3.4.5)
PowerPack: v2.0.x (the included FW_Updater updates to v2.0.9)

Pi/DENEB/DALIM:
- Improvements and bug corrections.

Change log:
v4.4.3.0
Required Firmware:
Pi/DENEB/DALIM: v3.4.x (the included FW_Updater updates Pi/DENEB/DALIM to v3.4.5)
PowerPack: v2.0.x (the included FW_Updater updates to v2.0.9)

Pi/DENEB/DALIM:

- New FIR bypass functionality in the *Mode* section.
- New configurable-latency FIR mode.
- Ability to restore a Mode within a Snapshot when the corresponding presets are available in the Speaker Presets Library.
- V-LAN support for operating amplifiers on separate V-LANs or through a VPN in remote locations.
- New keep-alive mechanism to detect disconnections and enable automatic reconnection.
- Faster Dante boot-up process.
- Improvements and bug corrections.

Change log:
v4.4.2.0
Required Firmware:
Pi/DENEB/DALIM: v3.4.x (the included FW_Updater updates Pi/DENEB/DALIM to v3.4.2)
PowerPack: v2.0.x (the included FW_Updater updates to v2.0.9)

Pi/DENEB/DALIM:

- New FIR bypass functionality in the *Mode* section.
- New configurable-latency FIR mode.
- Ability to restore a Mode within a Snapshot when the corresponding presets are available in the Speaker Presets Library.
- V-LAN support for operating amplifiers on separate V-LANs or through a VPN in remote locations.
- New keep-alive mechanism to detect disconnections and enable automatic reconnection.

- Faster Dante boot-up process.
- Improvements and bug corrections.

v4.3.7.2
Required Firmware:
Pi/DENEB/DALIM: v3.3.x (the included FW_Updater updates Pi/DENEB/DALIM to v3.3.11)
PowerPack: v2.0.x (the included FW_Updater updates to v2.0.6)

Pi/DENEB/DALIM:
- Improvements and bug corrections

v4.3.7.1
Required Firmware:
Pi/DENEB/DALIM: v3.3.x (the included FW_Updater updates Pi/DENEB/DALIM to v3.3.11)
PowerPack: v2.0.x (the included FW_Updater updates to v2.0.6)

Pi/DENEB/DALIM:
- New amplifier firmware version
- Improvements and bug corrections

v4.3.7.0
Required Firmware:
Pi/DENEB/DALIM: v3.3.x (the included FW_Updater updates Pi/DENEB/DALIM to v3.3.11)
PowerPack: v2.0.x (the included FW_Updater updates to v2.0.6)

Pi/DENEB/DALIM:
- New amplifier firmware version
- Improvements and bug corrections

v4.3.4.0
Required Firmware:
Pi/DENEB/DALIM: v3.3.x (the included FW_Updater updates Pi/DENEB/DALIM to v3.3.8)
PowerPack: v2.0.x (the included FW_Updater updates to v2.0.6)

Pi/DENEB/DALIM:
- New amplifier firmware version
- New Access Control to limit access to different functionalities
- New operating Modes (Lab, Tech, User) with control password
- Improvements and bug corrections

v4.2.9.2
Required Firmware:
Pi/DENEB/DALIM: v3.1.x (the included FW_Updater updates Pi/DENEB/DALIM to v3.1.18)
PowerPack: v2.0.x (the included FW_Updater updates to v2.0.3)

Pi/DENEB/DALIM:
- New amplifier firmware version
- Name assignation when creating a Snapshot in the amplifier display
- Improved encoder behavior in display dropdown
- RMS and Peak limiters are actives by default
- Ethernet communications improvements
- Bug corrections

v4.2.6.8
Required Firmware:
Pi/DENEB/DALIM: v3.1.x (the included FW_Updater updates to v3.1.15)
PowerPack: v2.0.x (the included FW_Updater updates to v2.0.3)

Pi/DENEB/DALIM Series window:
● Production requirements

v4.2.4.0
Required Firmware:
Pi/DENEB/DALIM: v3.1.x (the included FW_Updater updates to v3.1.5)
PowerPack: v2.0.x (the included FW_Updater updates to v2.0.3)

Overall
● New amplifier firmware version for Pi/DENEB/DALIM (v3.1.5)
● Possibility of reordering the devices in the tree by dragging
● Improved Q control in graphic windows
● Encrypted data in the Library and Preset files
  Advice! New Library/Preset files are not compatible with older software versions
● Communications API v1.1
● New access for amp properties change (only for service)
● Bug corrections

Pi/DENEB/DALIM Series window:
● Input Route/Matrix, with Advanced and Basic modes
● Backup Input for priority input systems
● All Pass filters in User EQ
● Outputs Mute after a Preset Load or Reset
● Device name up to 14 characters
● Group Mute removal using the amplifier display
● Window, layout and name changes
● Bug corrections

v4.0.10.1
Required Firmware:
Pi/DENEB/DALIM: v2.0.x (the included FW_Updater updates to v2.0.21)
PowerPack: v2.0.x (the included FW_Updater updates to v2.0.3)

● Resolve problem when loading Snapshots with taps in Fir filters
● Improves performance of shelving filters 6 dB's high-pass and low-pass
● Error in OCS when changing between channels in FIR filters is corrected
● In Model Pi, the error in the painting of the limiter vu-meters is corrected

v4.0.7
Required Firmware:

Pi/DENEB/DALIM: v2.0.x
PowerPack: v2.0.x
V: v2.9 (ADVICE: Latest version working with USB interface)